

DESCRIPTION OF EQUIPMENT:

Drywall Spray Texture Equipment.

1994 Mitsubishi FKMR

26,000 GVW 162,276 Miles

1000 Gal Split Tank

Power Take Off System

Two Hydraulic Texture Pumps

Hydraulic Motor Driving Two Curtis 89 Compressors.

1996 Mitsubishi FK

23,000 GVW 177,448 Miles

Complete Motor Rebuild at 173,211 Miles

800 Gallon 3 Split Tank

Power Take Off System

Hydraulic Motor Driving 1 Curtis 98 Compressor.

Three Hydraulic Texture Pumps.

2003 ISUZU NQR

18,000 GVW 133,146 Miles

Miles are not accurate. Odometer Spun When Equipment
was running on the back of Truck. Actual Highway Miles On Truck
is Aprox 50,000 – 60,000 Miles.

300 Gallon 2 Split Tank

Power Take Off System

Hydraulic Motor Drives 1 Curtis 98 Compressor.

Two Hydraulic Texture Pumps.

1995 Tag-Along 500 Gallon 2 Split Tank

Two Hydraulic Texture Pumps

30 HP Wesconson Motor Low Hours on Resent Rebuild.

Dayton Two Stage Air Compressor.

1997 Tag-Along 500 Gallon 2 Split Tank

Two Hydraulic Texture Pumps

37 HP Wesconson Motor Zero Hours on Resent Rebuild

Dayton Two Stage 15 HP Air Compressor.

Forklift, Hyster 3 Stage Forklift

3500 LBS Propane.